


## CERTIFICATE

The Inspection of School Building of D.A.V. Sr. Sec. School Baghni, Tehsil Nurpur, Distt. Kangra (HP). has been conducted by the Assistant Engineer, Sub Division, HP.PWD. Suliali accompanied with Junior Engineer. On the basis of their inspection report, it has been found that no Earthquakes resistant norms have been adopted for the construction of School building. No structural drawings approved by the competent Govt. agency were produced by the school authority. The structure of the building is a non Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc., if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the Building Safety Certificate is being issued by this Department from 1.4.2024 to 31.3.2025. This Department could not assess the structural safety of said building as the same was not constructed under the supervision of this Department.

  
Executive Engineer,  
Nurpur Division, HP.PWD.  
Nurpur